



U.S. Department
of Transportation
**Federal Aviation
Administration**

Advisory Circular

Subject: ACCEPTABLE METHODS,
TECHNIQUES, AND PRACTICES --
AIRCRAFT ALTERATIONS

Date: 10/30/89
Initiated by: AFS-340

AC No: AC 43.13-2A
Change: 2

1. PURPOSE. This Change corrects an editing error in issuance of "Change 1."

The Change number and date of the changed material are carried at the top of the page. Pages having no changes retain the same heading information.

2. PRINCIPAL CHANGES. Change 1, dated June 1, 1979, deleted paragraph 133. Paragraph 133 continued onto page 61, but this page was inadvertently left out in the page control chart to be removed. Therefore, this change corrects that error.

PAGE CONTROL CHART

| Remove Pages | Dated | Insert Pages | Dated |
|--------------|-----------|--------------|-----------|
| 61 | Rev. 1977 | 61 | 10/30/89 |
| 62 | Rev. 1977 | 62 | Rev. 1977 |

D. C. Beaudette
Acting Director, Flight Standards Service




FIGURE 8.6.—Tricycle gear aircraft.




FIGURE 8.7.—Conventional gear aircraft-leaf spring type tailwheel.